

G. K. I. C. LOG S.B.R. All interpretations are opinions based on inferences from electrical or other measurements and we cannot, and do not guarantee the accuracy or correctness of any inter pretations, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our General Terms and Conditions as set out in our current Price Schedule. BATTLESHIP FIELD TYPE LOG 057-06226 AFTER SURVEY TOOL CHECK SUMMARY over a site of the fill 82/05/20 PERFORMED: (YERSION 20.2 - 32/33/35) PROGRAM FILE: IES TOOL CHECK DITD **PLUS** ZERO AFTER UNITS BEFORE **AFTER** BEFORE MMHD 501.3 500.6 -0.0 0.0 ILD MMHO 498.0 497.0 -0.0 0.0 ILM MMHO 501.3 500.0 0.0 SFL SONDE ERROR CORRECTION : MMHD 6.3 ILD SONDE ERROR CORRECTION : MMHO 6.1 FILE 6 CHANGED PARAMETERS UNIT VALUE NAME UNIT VALUE NAME BS 8.750 IN ILD (DHWW) 50.00 0.0 <u>SFLA(DHMM)</u> 10.00 0.0 <u>SFLA(OHMM)</u> GR (GAPI) 50.00 200.0 0.0 0.0 CILD(MMHO) SP (MY) 0.0 2000 40.00 -160.0FILE BEST COPY AVAILABLE 300













