
From: Robert Morris [mailto:robert_morris@mhchew.com]
Sent: Thursday, May 17, 2012 7:50 AM
To: Fischer, Alex
Subject: FW: Sundry Federal 398-10-1 Radiological results

Here it is. I see that it was also sent to the RIOBLANCO.SUBMITTALS address. I sent my concurrence note there too.

Bob

From: Henry, Richard [mailto:richard.henry@urs.com]
Sent: Wednesday, May 16, 2012 4:18 PM
To: Danforth, Brandon
Cc: Kohler, Gretchen; robert_morris@mhchew.com
Subject: RE: Sundry Federal 398-10-1 Radiological results

All

FYI - Attached is the instrument calibration record Bob Morris requested. The instrument serial number is on the calibration record.

Richard

Richard Henry, PG
Principal Hydrogeochemist
URS Corporation
8181 East Tufts Avenue
Denver, CO 80237
303.740.3978 Direct
303.994.1747 Cell
richard.henry@urs.com

This e-mail and any attachments contain URS Corporation confidential information that may be proprietary or privileged. If you receive this message in error or are not the intended recipient, you should not retain, distribute, disclose or use any of this information and you should destroy the e-mail and any attachments or copies.

From: Danforth, Brandon [<mailto:Brandon.Danforth@wpenergy.com>]
Sent: Monday, May 14, 2012 10:42 AM
To: Henry, Richard
Cc: Kohler, Gretchen
Subject: FW: Sundry Federal 398-10-1 Radiological results

Richard – Please see Bob's comments below. Thanks,

Brandon Danforth
970.773.3166

From: Robert Morris [mailto:robert_morris@mhchew.com]
Sent: Monday, May 14, 2012 9:40 AM
To: Danforth, Brandon; alex.fischer@state.co.us; RioBlanco.submittal@state.co.us;
kevin.king@state.co.us; rick.hutton@lm.doe.gov; betty_lau@blm.gov
Subject: RE: Sundry Federal 398-10-1 Radiological results

Thanks.

This is as expected and is acceptable. Please be sure this information, along with details of the instrument serial number and calibration record, is included in the next public report submitted in accordance with the Rio Blanco SAP.

Bob Morris

Robert Morris, MS, CHP, CIH
Principal Health Physicist
M.H. Chew & Associates, Inc.
7985 Vance Dr Suite 307
Arvada, CO 80003

Robert_Morris@mhchew.com

303 424-0007 (office)
303 912-6225 (mobile)

From: Danforth, Brandon [mailto:Brandon.Danforth@wpenergy.com]
Sent: Monday, May 14, 2012 9:21 AM
To: robert_morris@mhchew.com; alex.fischer@state.co.us; Rioblanco.submittal@state.co.us;
kevin.king@state.co.us; rick.hutton@lm.doe.gov; betty_lau@blm.gov
Subject: FW: Sundry Federal 398-10-1 Radiological results

All – Please find Richard Henry's response below in regards to screening of the removed tubing.

Thanks,

Brandon Danforth
970.773.3166

From: Henry, Richard [mailto:richard.henry@urs.com]
Sent: Friday, May 04, 2012 10:50 AM
To: Danforth, Brandon
Subject: RE: Sundry Federal 398-10-1 Radiological results

Brandon

Sorry for the delay in responding, I was traveling last week and early this week.

Yes, the pipe removed from the hole was surveyed for radiation. The radiation screening survey was performed using a Ludlum 2401-EW Pocket Survey Meter equipped with an end window GM detector. The survey was performed by screening the length of selected pipes once they were removed from the hole and stacked. The instrument was held about 0.5 inches from the pipe while screening along its length. All radiation screening results were less than (<) 0.1 mR/hr or < 100 counts per minute (cpm). Background activity was also < 100 cpm or < 0.1 mR/h.

Let me know if you need any additional information.

Richard

Richard Henry, PG
Principal Hydrogeochemist
URS Corporation
8181 East Tufts Avenue
Denver, CO 80237
303.740.3978 Direct
303.994.1747 Cell
richard.henry@urs.com

you receive this message in error or are not the intended recipient, you should not retain, distribute, disclose or use any of this information and you should destroy the e-mail and any attachments or copies.

From: Danforth, Brandon [<mailto:Brandon.Danforth@wpenergy.com>]
Sent: Monday, April 30, 2012 7:41 AM
To: Henry, Richard
Subject: FW: Sundry Federal 398-10-1 Radiological results

Richard?

Brandon Danforth
970.773.3166

From: Robert Morris [mailto:robert_morris@mhchew.com]
Sent: Thursday, April 12, 2012 8:33 PM
To: Danforth, Brandon; alex.fischer@state.co.us; Rioblanco.submittal@state.co.us; kevin.king@state.co.us; rick.hutton@lm.doe.gov; betty_lau@blm.gov
Cc: Lindsay Sanders; Kohler, Gretchen; Foster, Greg
Subject: RE: Sundry Federal 398-10-1 Radiological results

This looks good.

Are contamination surveys of tubing made using a hand-held monitoring instrument available? I was informed during the recent site audit that the plan was to survey tubing and pipe prior to unrestricted release to landowner.

Bob Morris

Robert Morris, MS, CHP, CIH
Principal Health Physicist
M.H. Chew & Associates, Inc.
7985 Vance Dr Suite 307
Arvada, CO 80003

Robert_Morris@mhchew.com
303 424-0007 (office)
303 912-6225 (mobile)

From: Danforth, Brandon [<mailto:Brandon.Danforth@wpenergy.com>]
Sent: Thursday, April 12, 2012 2:02 PM
To: alex.fischer@state.co.us; Rioblanco.submittal@state.co.us; kevin.king@state.co.us; rick.hutton@lm.doe.gov; betty_lau@blm.gov; robert_morris@mhchew.com
Cc: Lindsay Sanders; Kohler, Gretchen; Foster, Greg
Subject: FW: Sundry Federal 398-10-1 Radiological results

Attached is the COGCC Sundry with radiological results from recent P&A operations at the Federal 398-10-1 well.

Thanks,

**NOTE - My new email address is brandon.danforth@wpxenergy.com
Please update your contacts, Thanks.**

Brandon Danforth | Environmental Specialist

WPX Energy Rocky Mountain, LLC | 1058 County Rd 215, Parachute, CO 81635

o: 970.263.2792 | c: 970.773.3166 | brandon.danforth@wpxenergy.com



If you have received this message in error, please reply to advise the sender of the error and then immediately delete this message.

From: Harris, Howard [<mailto:Howard.Harris@Williams.com>]

Sent: Monday, April 09, 2012 4:01 PM

To: Danforth, Brandon; Kohler, Gretchen; Foster, Greg; Shoemaker, Mike

Subject: Sundry Federal 398-10-1 Radiological results

The attached sundry and attachments was submitted to COGCC 4/9/12

Howard Harris

Sr. Regulatory Specialist

WPX Energy

Phone: (303) 606-4086

Fax: (303) 629-8272

E-mail: Howard.Harris@Williams.com