

Surface Casing Pressures
WillSource Enterprise

API #	Well Name	Casing	Date	Initial Pressure	Comments	Fluid Type	Final Pressure	Csg Depth	Top Of Cement	Initial Gradient at Shoe	Action Required	Request to Vent Approved	Current Venting Status
077-08712	Willsource 1-13	Surface	10/13/2017	0	Braden pressure: It was at ZERO psi (initial and final pressure)	NA	0	462'	Surface	0	No	No	SI
077-08712	Willsource 1-13	Inter	10/13/2017	0		NA	0	2395'	150'	0.00	No	No	SI

Checked Casing pressure: It was at **263 psig**.
Checked Tubing pressure: It was at **248 psig**.