## MARALEX RESOURCES, INC. SURFACE CASING REPORT - 2014

| API#       | Well Name  | Casina            | Date     | Casing<br>back<br>pressure | Comments   | Fluid Type | Casing<br>Depth |
|------------|--|-------------------|----------|----------------------------|--|------------|-----------------|
| 0504506127 | Rifle Boulton #1 NWNW<br>23 T7S R91W Garfield<br>County  | Casing<br>Surface | 10/06/14 | 0                          | surface casing piped to tank, no flow of fluid, very slight gas vapors, no pressure                                  | none       | 243             |
| 0504506290 | Rifle Walton 25-2 SENW<br>25 T7S R91W Garfield<br>County | Surface           | 10/06/14 | 55                         | surface casing piped to tank, flowing 8 bwpd on ¼" choke holding 53 to 55 psig back pressure with no measureable gas | water      | 309             |
| 0504506213 | Federal 26-3 NWSW<br>26 T7S R91W Garfield<br>County      | Surface           | 10/06/14 | 70                         | surface casing piped to tank, flowing 2 bwpd on ¼" choke holding 30 to 70 psig back pressure with no measureable gas | water      | 450             |
|            |  |                   |          |                            |  |            |                 |
|            |  |                   |          |                            |  |            |                 |
|            |  |                   |          |                            |  |            |                 |
|            |  |                   |          |                            |  |            |                 |
|            |  |                   |          |                            |  |            |                 |
|            |  |                   |          |                            |  |            |                 |